

## **“Metal Whiskers” Does Surface Contamination Have an Effect of Whisker Formation?**

**Terry Munson / Paco Solis**  
Foresite Inc.  
Kokomo Indiana

### **Abstract:**

Foresite has investigated many whisker failures and found that consistent high levels of chloride, sulfate and amines are present in and around the areas of whisker formation even in hot dry environments with high stress conditions in the solder joints.

### **Introduction:**


Using new techniques to extract pockets of contamination to isolate a specific area we can qualify the ionic residues on the surface and at the subsurface level. We will show supporting evidence that localized levels of contamination have an effect on the dissolution and stress conditions that feed whisker formations.

This paper will review some select failures due to metal whisker formations shorting and data of controlled whisker growth under contamination and now growth under clean conditions of plated and solders surfaces. Devices are not shown in their original failure state to honor client – consultant NDAs.

### **Case History #1**

#### **Zinc Whiskers on raised ESD floor tiles**

- ICT hardware on a raised ESD flooring system was found to have intermittent electrical issues with power supplies.
- Transformers and power busses were being shorted by an accumulation of zinc formations carried by cooling fans into system architectures.
- These issues were found to coincide with janitor mopping activity of the ESD floor.




**Figure 1 - Tin whisker on zinc alloy ESD floor tile**

### **Findings from Initial Case History**

- These whiskers are the result of a highly Sulfonated / Amine bearing mop water solution (validated by Ion Chromatography testing). ESD Soap!
- On tiles where these ionic residues have been removed by remedial cleaning and rinsing (with proper chemistries), the whisker formations are greatly retarded or completely eliminated.
- Contaminated tiles in our lab continue to produce whiskers to this day.


### **Case history #2 SAC 304 Alloy**

- SOT Device in high density SMT PCA
- SAC304 Alloy
- Dry Warm Conditions
- Formation in 2-3 weeks




**Figure 2- Whiskers on SOT gull lead with SAC 304 alloy termination**

During reflow, high concentrations of flux residues flow up the termination and accumulate at the gull wing bend. Although solder reflow occurs from toe to shoulder, the flux accumulation settles at the lead bend. A second item noted was the discovery of nano-whiskers which form from the flux line extending over 200  $\mu\text{m}$  in serpentine length and under 1  $\mu\text{m}$  in width.




**Figure 3 - SEM Image of SOT gull wing termination**




**Figure 4 & 5 - SEM Image of primary and Nano-Whiskers**

These nano-whiskers continuously extrude from the surface as well as from the larger primary whiskers. They settle on the surface and are freely fractured and fall away with little force.



**Figure 6 & 7 - SEM Image of primary and Nano-Whiskers**

In the below cross-section image these whiskers were recorded showing surface and subsurface attributes to their formation.




**Figure 8 – Optical Image of primary whisker in cross-section**



**Figure 9 – Optical Image primary whisker in cross-section at 1000X**

In cross-section a single grain dislocation can be seen at the whisker extrusion site. More samples like these are needed to further study this condition. This sample was prepared with pH 9 gamma colloidal silica slurry for grain delineation. The sample was unfortunately compromised before it was submitted to SEM analysis.



**Figure 10 – Optical Image of primary whisker in cross-section at 1000X (digitally magnified)**



# Chemical analysis data:

Analysis samples for ion chromatography were collected with the C3 cleanliness test system.



**Figure 11 –Cleanliness test system**


The ion chromatography data below shows high Chloride, sulfate, and Ammonia contaminations coinciding with the highest occurrences and density of whisker growth (shown in red).

**Table 1**


all values are in ug/in2		Ion Chromatography			
Sample Area	Location	Chloride	Sulfate	Ammonia	WOA
<b>Assembly SN 4YQ5006T</b>					
Q10 area	Via	3.91	2.04	0	0
	Pads	4.11	1.47	2.34	21.02
	Component	2.14	0.24	1.21	11.74
Q8 area	Via	4.15	1.68	0	0
	Pads	3.98	0.74	0	12.36
	Component	1.41	0.11	0	8.69
R7 area	pads	2.11	1.69	0	17.95
	component	1.79	0.47	0	4.75
U1 area (14pin DIP)	Via	3.14	2.11	0	0
	Pads	2.47	0.67	0	22.61
	Component	2.04	0	0	9.17
Refence 8 pin DIP	Via	3.77	1.21	0	0
	Pads	2.11	0.69	0.47	15.42
	Component	1.36	0	0.26	10.41
Reference Board no via area	Board	1.79	1.02	1.01	10.63

**Table 2**


all values are in ug/in2		Ion Chromatography			
Sample Area	Location	Chloride	Sulfate	Ammonia	WOA
<b>Assembly SN 4YQ5006S</b>					
Q10 area	Via	4.85	3.11	0	0
	Pads	3.98	2.74	2.32	24.36
	Component	1.24	0	3.11	19.54
Q8 area	Via	1.22	1.44	0	0
	Pads	0.95	0.36	0	16.24
	Component	0.77	0	0	11.47
R7 area	pads	1.69	1.04	0	15.24
	component	1.55	0	0	6.96
U1 area (14pin DIP)	Via	1.05	0.77	0	0
	Pads	0.78	0.59	0.85	20.04
	Component	0.36	0	1.21	7.87
Refence 8 pin DIP	Via	2.04	1.11	0	0
	Pads	0.69	0.45	2.41	18.65
	Component	0.27	0	2.95	14.21
Reference Board	Board	1.24	0.14	1.02	14.25
no via area					




**Figure 12**



**Figure 13**




**Figure 14**



**Figure 15**

Preliminary findings from Case History #2

- Localized D.I. steam cleaning with a saponifier has proven effective at preventing reoccurrences when total ionic contamination has been reduced.
- Inversely - areas doped with high levels of ionic contamination show a significantly higher occurrence of whisker formations.



**Figure 16 – Results of accelerated whisker growth from select doping of terminations**

### Current analysis Case history #3 Tin whiskers in D-sub jack screw

Whiskers are forming in the jack screws of lead free connectors. Preliminary data has shown high levels of Chlorides, Sulfates, and Amines are present in the Jack Screws. Analysis is ongoing to study the contamination effects in these locations and the retardation effects of cleaning. Data on this analysis is will published in updates to this paper.




Figure 17 – optical images of whiskers on jack screw threads





Figure 18 & 19 – optical images of whiskers on jack screw threads

#### Where do we go now?

- Continue to collect data points
- DOE in progress to recreate the failure mode at-will with a vehicle to better understand the activation energy, contamination thresholds, and stresses for the whisker formation.
- Preliminary findings have lead to a grant awarded to continue research.
- Return next year with an update!